



JXS-037C

Two-head And Three-head
Accessories Combination

USER MANUAL



CAUTION! Read all precautions and instructions in this manual before using this equipment.

Read all precautions and instructions in this manual before using this equipment

Assembly Caution	-----	3
Accessories Assembly List	-----	4
Step 1	-----	5

ASSEMBLY CAUTION

Please carefully read the following information before installation

Assembling requires at least two people

Do not tighten all screws before assembly is complete

Ensure that all accessories are complete. If not, please contact us via email




If you are missing any parts, or otherwise have any warranty issues, please contact us first.

Shortcut: A Lot of People Doing That Way


To enhance your installation process for both speed and convenience, consider removing all accessories from the box, carefully opening the packaging, and arranging everything neatly on the floor. This preparation can streamline your setup experience.

The following tools might help you improve your installation experience


- Adjustable wrenches




- Rubber hammers



- Socket set



- Electric Wrench



WARNING



Choking hazard. Small parts-Please exercise caution if small children or pets are present.













Sharp objects may be involved. Use precaution and protection.







Heavy object. Use lifting aids and proper lifting techniques when moving

Accessories Assembly List

1 Elbow pad assembly 1PC 	2 Washers $\Phi 8$ 6PCS 	3 Washers $\Phi 12$ 2PCS 	4 Spring washer $\Phi 8$ 6PCS 
5 Spring washer $\Phi 12$ 2PCS 	6 Hex socket head screw M8×30 6PCS 	7 Arm strength pad 1PC 	8 Adjust welding components 1PC 
9 Hex socket head screw M12×30 2PCS 	10 Adjust core weld assembly 1PC 		

Accessories Installation STEP: 2

1 Elbow pad assembly 1PC 	2 Washers $\Phi 8$ 6PCS 	3 Washers $\Phi 12$ 2PCS 	4 Spring washer $\Phi 8$ 6PCS 	5 Spring washer $\Phi 12$ 2PCS 	6 Hex socket head screw M8x30 6PCS 
7 Arm strength pad 1PC 	8 Adjust welding components 1PC 	9 Hex socket head screw M12x30 2PCS 	10 Adjust core weld assembly 1PC 		



SKEISO

